



June 5, 1958

Dear Al:

In connection with your report #94 we have recommended to the project that they do not try to go into this flow bench check for the obvious reasons. Instead we have recommended as you indicate in your last paragraph a simple, flowmeter of greater accuracy than the installation counter. I am enclosing a copy of our letter to the project on this.

We have been accumulating additional experience on controls that have been set and glyptol sealed. We concur with your observation that we have not seen any shift. We believe periodic min flow check is part of the overall effort to achieve maximum operational reliability and is not based on any new experience.

We don't know about the flow meter in the article but will find out.

Regards,

JHG

cc: RLC  
WHB

DOCUMENT NO. 36  
NO CHANGE IN CLASS. ☒  
☐ RECLASSIFIED  
CLASS. & EXT. BY: TS 303  
EXT. & EXT. DATE: 201  
AUTH: ME TB-2  
DATE: 6/11/81 REVIEWER: 008632